

Commercial Anchors • Loop Top Fixtures

Loop Top and Pass Through PID Labels

Permanent and replaceable PID labels and inspection labels are supplied with each Loop Top and Pass Through fixture. Bolt through and Stud bolt attached fixtures are attached between the fixture base and the supporting structure during installation. Field welded fixtures require labels to be attached after welding and are supplied with a provisional label pack that is removed prior to welding and may be re-attached after welding. For long term use of field welded fixtures, permanently attached label packs are supplied as an option and are attached with a stainless steel hex head bolt and flat washer.

- PID Labels are YYYY-MM dated at the time of sale
- Customer to specify permanent label pack option at time of ordering

Field Weld Attached Labels

Provisional Label Pack

Zip Tie attached Label Packs are removed prior to welding and re-attached after welding. Includes an extra zip tie.



SST Bolt and Washer



1/4" Bolt Hole For Label Attachment



Label Pack attached after welding

Optional Hex Bolt Attached Label Packs

Supplied with threaded bolt hole, label pack, stainless steel hex bolt and washer. Attach after field welding.

Through Bolt and Stud Bolt Labels


Labels attach between the fixture base and the supporting structure.

Field Weld Labels


Through Bolt Fixture
PID Label

Stud Bolt Fixture
PID Label

PID Label
Grommet



2 Inspection Labels



2 Inspection Labels



2 Inspection Labels