

## Leg Strap

Fig.15a Leg Strap Outside

➔ = Stitching Inspection



Fig.15b Leg Strap Inside



## D-Pad Broken Stitching 20

Broken Stitching Remove Harness From Service, ☒

Fig.17a 3



Fig.17b 3




Fig.16a Frame Binding 20



Fig.16b



Fig.16c



## Webbing Damage 20

Fig.18a



Fig.18b



Fig.18c



Fig.20 Corrosion

11 12 13 14



## Web-Ends 16

Webbing Fed Thru QC and AB Buckles

Fig.19a



Fig.19b



Fig.19c




Fig.21 Connector Coatings

